

REPAIR KIT

For use on:

Graco:

GMax 3900, GMax II 3900
UltraMax 795 & 1095
UltraMax II 695 & 795
LineLazer II/III/IV 3900

Replaces:

Graco No. 248-212

Manufactured by:

BEDFORD
PRECISION PARTS

BEDFORD HILLS, NEW YORK

MADE IN USA

REPAIR KIT

20-2662

For use on:

Graco:

GMax 3900, GMax II 3900
UltraMax 795 & 1095
UltraMax II 695 & 795
LineLazer II/III/IV 3900

Replaces:

Graco No. 248-212

Manufactured by:

BEDFORD
PRECISION PARTS

BEDFORD HILLS, NEW YORK



6

63547 02662

1

MADE IN USA

PARTS INCLUDED

QUANTITY REQUIRED	BEDFORD PART NO.	REPLACES GRACO PART NO.	PART DESCRIPTION
1	9-140	105-444	Ball, piston
1	9-183	105-445	Ball, intake
2	1-1242	178-939	Leather V-Packing, lower
2	1-1243	178-940	Leather V-Packing, upper
1	18-1299	178-969	Female Gland, lower
2	15-1498	108-526	Teflon O-Ring
1	15-2278	107-079	Teflon O-Ring
1	0-2284	114-054	O-Ring
3	49-2285	192-692	Polyethylene V-Packing, upper
3	49-2286	192-693	Polyethylene V-Packing, lower
1	17-2422	179-810	Plug
1	18-2426	196-880	Male Gland, lower
1	0-2657	118-494	O-Ring, Viton
1	52-2658	118-503	Wiper
1	18-2659	15C-987	Male Gland, upper
1	18-2660	15C-988	Female Gland, upper
1	10-2661	15C-997	Backup Washer
1	0-2758	158-776	O-Ring, throat spacer

REPAIR KIT


For use on:

Graco:

GMax 3900, GMax II 3900
UltraMax 795 & 1095
UltraMax II 695 & 795
LineLazer II/III/IV 3900

Replaces:

Graco No. 248-212



Before attempting any maintenance, carefully read all instructions and warnings in the Graco instruction sheets that came with your particular unit.